

## HAAS C.N.C. MILL PREPARATORY FUNCTIONS

MODAL  
NON-MODAL  
DEFAULT \*

G00* RAPID MOTION (X,Y,Z,A,B)	G68 ROTATION (G17,G18,G19,X,Y,Z,R)
G01 LINEAR INTERPOLATION MOTION (X,Y,Z,A,B,F)	G69* CANCEL G68
G02 CW CIRCULAR INTERPOLATION MOTION (X,Y,Z,A,I,J,K,R,F)	G70 BOLT HOLE CIRCLE (I,J,L)
G03 CCW CIRCULAR INTERPOLATION MOTION (X,Y,Z,A,I,J,K,R,F)	G71 BOLT HOLE ARC (I,J,K,L)
G04 DWELL (P) (P=seconds*.milliseconds)	G72 BOLT HOLES ALONG AN ANGLE (I,J,L)
G09 EXACT STOP	G73 HIGH SPEED PECK DRILL CANNED CYCLE (X,Y,A,B,Z,I,J,K,Q,PR,F)
G10 PROGRAMMABLE OFFSET SETTING (X,Y,Z,A,L,P,R)	G74 REVERSE TAPPING CANNED CYCLE (X,Y,A,B,Z,R,F)
G12 CW CIRCULAR POCKET MILLING (Z,D,I,K,L,Q,F)	G76 FINE BORING CANNED CYCLE (X,Y,A,B,Z,I,J,P,Q,R,F)
G13 CCW CIRCULAR POCKET MILLING (Z,D,I,K,L,Q,F)	G77 BACK BORE CANNED CYCLE (X,Y,A,B,Z,I,J,Q,R,F)
G17* CIRCULAR MOTION XY PLANE SELECTION	G80* CANNED CYCLE CANCEL
G18 CIRCULAR MOTION ZX PLANE SELECTION	G81 DRILL CANNED CYCLE (X,Y,A,B,Z,R,F)
G19 CIRCULAR MOTION YZ PLANE SELECTION	G82 SPOT DRILL / COUNTERBORE CANNED CYCLE (X,Y,A,B,Z,PR,F)
G20* INCH COORDINATE POSITIONING SELECTION	G83 PECK DRILL CANNED CYCLE (X,Y,A,B,Z,I,J,K,Q,PR,F)
G21 METRIC COORDINATE POSITIONING SELECTION	G84 TAPPING CANNED CYCLE (X,Y,A,B,Z,R,F)
G28 RETURN TO MACHINE ZERO THRU REF. POINT (X,Y,Z,B)	G85 BORE IN, BORE OUT CANNED CYCLE (X,Y,A,B,Z,R,F)
G29 MOVE TO LOCATION THRU G29 REFERENCE POINT (X,Y,Z,A)	G86 BORE IN, STOP, RAPID OUT CANNED CYCLE (X,Y,A,B,Z,R,F)
G31 FEED UNTIL SKIP FUNCTION (X,Y,Z,A,B,F)	G87 BORE IN AND MANUAL RETRACT CANNED CYCLE (X,Y,A,B,Z,R,F)
G35 AUTOMATIC TOOL DIAMETER MEASUREMENT (D,H,Z,F)	G88 BORE IN, DWELL, MANUAL RETRACT CANNED CYCLE (X,Y,A,B,Z,PR,F)
G36 AUTOMATIC WORK OFFSET MEASUREMENT (X,Y,Z,A,B,I,J,K,F)	G89 BORE IN, DWELL, BORE OUT (X,Y,A,B,Z,PR,F)
G37 AUTOMATIC TOOL LENGTH MEASUREMENT (D,H,Z,F)	G90* ABSOLUTE POSITION COMMAND
G40* CUTTER COMP CANCEL G41/G42/G141 (X,Y)	G91 INCREMENTAL POSITION COMMAND
G41 CUTTER COMPENSATION LEFT (X,Y,D)	G92 SET WORK COORDINATE SHIFT VALUE (HAAS) (FANUC)
G42 CUTTER COMPENSATION RIGHT (X,Y,D)	G92 SET WORK COORDINATE SHIFT VALUE (YASNAC)
G43 TOOL LENGTH COMPENSATION+ (H,Z)	G93 INVERSE TIME FEED MODE ON
G44 TOOL LENGTH COMPENSATION- (H,Z)	G94 INVERSE TIME FEED MODE OFF / FEED PER MINUTE ON
G47 TEXT ENGRAVING (X,Y,Z,R,I,J,P,E,F)	G98* CANNED CYCLE INITIAL POINT RETURN
G49* CANCEL G43/G44/G143	G99 CANNED CYCLE "R" PLANE RETURN
G50 CANCEL G51	G100 CANCEL MIRROR IMAGE (X,Y,Z,A,B)
G51 SCALING (X,Y,Z,P)	G101 ENABLE MIRROR IMAGE (X,Y,Z,A,B)
G52 SET WORK COORDINATE SYSTEM G52 (YASNAC)	G102 PROGRAMMABLE OUTPUT TO RS-232 (X,Y,Z,A,B)
G52 SET LOCAL COORDINATE SYSTEM (HAAS) (FANUC)	G103 LIMIT BLOCK BUFFERING (P0-P15 for number control looks ahead)
G53 NON-MODAL COORDINATE SELECTION (X,Y,Z,A,B)	G107 CYLINDRICAL MAPPING (X,Y,Z,A,Q,R)
G54* SET WORK COORDINATE SYSTEM 1	G110-G129 WORK OFFSET COORDINATE SYSTEM #7-26
G55 SET WORK COORDINATE SYSTEM 2	G143 5 AXES TOOL LENGTH COMPENSATION+ (H,Z)
G56 SET WORK COORDINATE SYSTEM 3	G136 AUTOMATIC WORK OFFSET CENTER MEASUREMENT
G57 SET WORK COORDINATE SYSTEM 4	G141 3D+ CUTTER COMPENSATION (X,Y,Z,I,J,K,D,F)
G58 SET WORK COORDINATE SYSTEM 5	G143 5 AXES TOOL LENGTH COMPENSATION+ (X,Y,Z,A,B,H)
G59 SET WORK COORDINATE SYSTEM 6	G150 GENERAL PURPOSE POCKET MILLING (X,Y,Z,I,J,K,L,Q,P,D,R,S,F)
G60 UNIDIRECTIONAL POSITIONING	G174 VECTOR RIGID TAPPING CCW (X,Y,Z,F)
G61 EXACT STOP MODAL	G184 VECTOR RIGID TAPPING CW (X,Y,Z,F)
G64* CANCEL G61	G187 ACCURACY CONTROL FOR HIGH SPEED MACHINING (E)
G65 MACRO SUB ROUTINE CALL	

## HAAS C.N.C. MILL MISCELLANEOUS FUNCTIONS

M00 PROGRAM STOP	M36 PALLET PART READY
M01 OPTIONAL PROGRAM STOP	M39 ROTATE TOOL TURRET (T)
M02 PROGRAM END	M41 LOW GEAR OVERRIDE
M03 SPINDLE ON CLOCKWISE (S)	M42 HIGH GEAR OVERRIDE
M04 SPINDLE ON COUNTERCLOCKWISE (S)	M50 EXECUTE PALLET CHANGE
M05 SPINDLE STOP	M51-M58 OPTIONAL USER M TURN ON
M06 TOOL CHANGE (T)	M61-M68 OPTIONAL USER M TURN OFF
M08 COOLANT ON	M67 RELEASE FIFTH AXIS BRAKE, PROGRAM CONTINUES
M09 COOLANT OFF	M75 SET G35 OR G136 REFERENCE POINT
M10 ENGAGE 4th AXIS BRAKE	M76 DISABLE DISPLAYS
M11 RELEASE 4th AXIS BRAKE	M77 ENABLE DISPLAYS
M12 ENGAGE 5th AXIS BRAKE	M78 ALARM IF SKIP SIGNAL FOUND
M13 RELEASE 5th AXIS BRAKE	M79 ALARM IF SKIP SIGNAL NOT FOUND
M16 TOOL CHANGE (same as M06) (T)	M82 TOOL UNCLAMP
M19 ORIENT SPINDLE	M86 TOOL CLAMP
M21-M28 OPTIONAL PULSED USER M FUNCTION WITH FIN	M88 THRU SPINDLE COOLANT ON
M30 PROGRAM END AND REWIND	M89 THRU SPINDLE COOLANT OFF
M31 CHIP CONVEYOR FORWARD	M95 SLEEP MODE
M32 CHIP CONVEYOR REVERSE	M96 JUMP IF NO SIGNAL (P,Q)
M33 CHIP CONVEYOR STOP	M97 LOCAL SUB-ROUTINE CALL (P,L)
M34 INCREMENT COOLANT SPIGOT POSITION	M98 SUB-PROGRAM CALL (P,L)
M35 DECREMENT COOLANT SPIGOT POSITION	M99 SUB-PROGRAM/ROUTINE RETURN OR LOOP

All M codes are effective or cause an action at the end of the block and only one M code is allowed in each block.

