

Photos Taken for Week Ended 11-07-08

Contents

North and East Façade from NE Corner ..... 2

East Façade ..... 3

South Façade (East Half) from Access Road..... 4

South Façade (West Half) from Access Road..... 5

West Façade from Parking Lot..... 6

North and West Façade from NW Corner..... 7

1<sup>st</sup> Floor Lobby..... 8

4<sup>th</sup> Floor – Unit 404 ..... 9

10<sup>th</sup> Floor – Demising Wall ..... 10

10<sup>th</sup> Floor – Metal Lathe over CFRP on Slab..... 11

11<sup>th</sup> Floor – Floor Leveling..... 12

15<sup>th</sup> Floor – Framing ..... 13

20<sup>th</sup> Floor Roof – NW Corner..... 14

**North and East Façade from NE Corner**



**East Façade**



**South Façade (East Half) from Access Road**



**South Façade (West Half) from Access Road**



**West Façade from Parking Lot**



**North and West Façade from NW Corner**



**1<sup>st</sup> Floor Lobby**





**4<sup>th</sup> Floor – Unit 404**



**10<sup>th</sup> Floor – Demising Wall**



**10<sup>th</sup> Floor – Metal Lathe over CFRP on Slab**



**11<sup>th</sup> Floor – Floor Leveling**



**15<sup>th</sup> Floor – Framing**



**20<sup>th</sup> Floor Roof – NW Corner**

