

Photos Taken for Week Ended 10-03-08

Contents

North and East Façade from NE Corner 2

East Façade 3

South Façade (East Half) from Access Road..... 4

South Façade (West Half) from Access Road..... 5

West Façade from Parking Lot..... 6

North and West Façade from NW Corner..... 7

1st Floor Lobby – Framing Stair C 8

6th Floor – Stair B Framing (Poured Through 6th Floor)..... 9

6th Floor – Framing Demising Walls 10

8th Floor – Floor Leveling..... 11

15th Floor – Stocking Floor 12

19th Floor Storefront – NE Façade..... 13

North and East Façade from NE Corner



East Façade



South Façade (East Half) from Access Road



South Façade (West Half) from Access Road



West Façade from Parking Lot



North and West Façade from NW Corner



1st Floor Lobby – Framing Stair C



6th Floor – Stair B Framing (Poured Through 6th Floor)



6th Floor – Framing Demising Walls



8th Floor – Floor Leveling



15th Floor – Stocking Floor



19th Floor Storefront – NE Façade

