

Photos Taken for Week Ended 10-31-08

Contents

North and East Façade from NE Corner 2

East Façade 3

South Façade (East Half) from Access Road..... 4

South Façade (West Half) from Access Road..... 5

West Façade from Parking Lot..... 6

North and West Façade from NW Corner..... 7

1st Floor Lobby – From Top of Stair C..... 8

2nd Floor (East) – Store Front Mullions/Stone Support Brackets 9

Mockup Unit 304 – Prime Coat..... 10

9th Floor – Demising Wall (D-E Line)..... 11

11th Floor – Floor Leveling (North Side) 12

12th Floor – Stair B Poured to 13th Floor 13

20th Floor Roof – NW Corner..... 14

North and East Façade from NE Corner



East Façade



South Façade (East Half) from Access Road



South Façade (West Half) from Access Road



West Façade from Parking Lot



North and West Façade from NW Corner



1st Floor Lobby – From Top of Stair C



2nd Floor (East) – Store Front Mullions/Stone Support Brackets



Mockup Unit 304 – Prime Coat



9th Floor – Demising Wall (D-E Line)



11th Floor – Floor Leveling (North Side)



12th Floor – Stair B Poured to 13th Floor



20th Floor Roof – NW Corner

