

The Pennsylvania State University HUB Addition and Renovation University Park, PA







Work In Progress

- Site Clearing & Demolition at Grange Building
- Temporary Walls (B2 & Ground Floor)
- Completed Egress Work through Robeson Center
- Fixture/Fire Alarm Demolition for Temporary Walls
- Interior Architectural and MEP Demolition in Bookstore
- Bookstore Storage Trailers






HUB Parking Deck View















Top of Parking Deck View







South Entrance View









Bookstore Loading Dock View








Interior Demolition













Planned Work

- Continue Architectural and MEP Demolition in Bookstore
- Continue Sitework at Grange Building
- Begin Façade Demolition in Courtyard
- Begin Demolition in Lower Lobby

