

**Photos Taken for Week Ended 12-19-08**

**Contents**

North and East Façade from NE Corner ..... 2

East Façade ..... 3

South Façade (East Half) from Access Road..... 4

South Façade (West Half) from Access Road..... 5

West Façade from Parking Lot..... 6

North and West Façade from NW Corner..... 7

1<sup>st</sup> Floor Lobby (From Stair C)..... 8

Unit 304 – Kitchen Area ..... 9

4<sup>th</sup> Floor – Installing Tile ..... 10

5<sup>th</sup> Floor – Unit Doors and Trim ..... 11

8<sup>th</sup> Floor – Hanging Drywall..... 12

17<sup>th</sup> Floor – Framing Demising Wall (NE Corner) ..... 13

20<sup>th</sup> Floor – NE Corner..... 14

**North and East Façade from NE Corner**



**East Façade**



**South Façade (East Half) from Access Road**



**South Façade (West Half) from Access Road**



**West Façade from Parking Lot**



North and West Façade from NW Corner



**1<sup>st</sup> Floor Lobby (From Stair C)**





**Unit 304 – Kitchen Area**



**4<sup>th</sup> Floor – Installing Tile**



**5<sup>th</sup> Floor – Unit Doors and Trim**



**8<sup>th</sup> Floor – Hanging Drywall**



**17<sup>th</sup> Floor – Framing Demising Wall (NE Corner)**



**20<sup>th</sup> Floor – NE Corner**

